HP 932/933 HP950/951 Chip Replacement

1) Remove the OEM chip using a sharp knife.



2) The Ausjet chip is larger than the OEM chip. To install a new chip the cartridge will need to be modified. The highlighted area will need to be cut out to a depth 1mm below the top level of the cartridge.



3) Photo of cut out area ready for chip placement. (Please note the square hole in the cutout is not required)



4) Photo of OEM HP932XL with Ausjet chip installed after the cartridge has been modified.



* Compatible and remanufactured HP932/933 & HP950/951 with new chip are also now available.