

<b>Cartridge:</b>	<b>BCI-61</b>	<b>Cartridge Wt. New:</b>	128 g –132 g
<b>OEM:</b>	<b>Canon</b>	<b>Printer:</b>	BJC-7000, BJC-7100
<b>Printhead Location:</b>	Disposable	<b>Cartridge Type:</b>	Sponge
<b>Reliability:</b>	*****	<b>Skill Level:</b>	Novice




Fig. 2.26

© Ausjet Ink Jet Supplies and Service Pty Ltd

## COMMENTS

The BC-61 is a tri-colour cartridge tank which clicks into a print head unit. In this method we drip ink on to the ink path holes. If you prefer you may drip through the back of the cartridge and inject ink into the chambers. Very easy to refill. The BJC 7100 is an excellent printer with a fabulous cleaning mechanism

## REQUIREMENTS

- ◆ 0-20 ml each Cyan ,Magenta ,Yellow Inks. (Refer to Ausjet Ink Selector)
- ◆ 3 x 20 ml syringes

## REFILLING METHOD

### STEP 1.

Locate the ink path holes on the underside of the cartridge. Start with the yellow ink and drip up to 20 ml of ink onto the yellow ink path hole. When the sponge ceases to accept ink, turn over the cartridge and let any excess drain off. After dripping stops seal the port with tape to prevent accidents.

### STEP 2.

Clean, if necessary and then repeat Step 1 until all chambers are full. Make sure all ports are sealed for shipping.